

Amendments to the Specification:

Please amend paragraph 0026 to read as follows:

[0026] The support 23 has a widened rear panel 30, which fills the height of the open side ~~[[10]]~~ 21. Drill holes of the rear panel 30 come to lie in front of ribs, which are provided with a threaded hole and project from the upper and lower side 8, 9 into the interior of the housing module 6, and allow the housing module 6 and the coupling mechanism module 22 to be screwed together.

Please amend paragraph 0027 to read as follows:

[0027] As may be easily imagined from the figure, the rear panel 30 does not fill the open side ~~[[10]]~~ 21 over its entire length in the assembled state. Two windows remain at each end, through which locking pins 31 are passed through the holes 27 of the journals 26 and U-shaped cutouts 32 of the tongues 29 in order to secure the shaft sections ~~10 to 14~~ 10, 11, 12, 13 to the shafts of the pulleys 24, 25 and bring their axes precisely into line.